

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

EN697
East
1/2-1
0.997 mi.
5263 ft.

COMMERCIAL SITE
3140 CONEY ISLAND AVE
BROOKLYN, NY

NY Spills S118707057
N/A

Site 3 of 4 in cluster EN

Relative:
Higher

Actual:
9 ft.

SPILLS:

Name: COMMERCIAL SITE
Address: 3140 CONEY ISLAND AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1604244 / 2018-02-26
Facility ID: 1604244
Facility Type: ER
DER Facility ID: 341547
Site ID: 530742
DEC Region: 2
Spill Cause: Unknown
Spill Class: Not reported
SWIS: 2401
Spill Date: 2016-07-27
Investigator: YYWONG
Referred To: Not reported
Reported to Dept: 2016-07-28
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2016-07-28
Spill Record Last Update: 2018-02-27
Spiller Name: Not reported
Spiller Company: 3140 CONEY ISLAND AVE
Spiller Address: Not reported
Spiller Company: 999
Contact Name: JENNIFER LEWIS
DEC Memo: "7/28/16 - Desk Duty - Obligado - This is a BCP site under Bryan Wong. There is free product in well. Spill assigned to Bryan Wong.
8/22/16 - Jennifer Lewis, PW grosser, email DEC indicated that they were out at the site last week to gauge the MW-16, where LNAPL was detected, and absorbent sock, and weekly visit to continue recover the LANPL from this 1 inches well via sock or peristaltic pump. The product recovery will be place in container stored on site until no more product detected in the well. (B.W.) 8/24/16 PW grosser staff visit the site on 8/23/16 and report that only a sheen of oil was present at MW-16. absorbent sheet were lowered into the well and recovered until oil was no longer present. the recovered oil were placed in an on-site container for eventual off-site disposal. (B.W.) 1/22/18 PW Grosser sent in letter request to close the spill based on work done from august 2016 to December 2017. The letter stated that groundwater sample from the two wells MW-16 and MW-17 did not contained exceedance of petroleum related compounds. the reported sheen on LNAPL in MW-16 were only noted in the interface probe, no solid tone were noted due to limited LNAPL in the well. absorbent sock had been use to try to remove sheen of LNAPL from MW-16. 2/14/18 discussed with management with the data present in PW grosser 1/22/18

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

letter, it is recommend that the spill be closed and the MW-17 will
be use to replace the MW-16 for the GW monitoring under the BCP site
C224157 site management plan. (B.W.) 2/26/18 spill closure letter
issued (B.W.) "

Remarks:

"clean up pending"

All Materials:

Site ID: 530742
Operable Unit ID: 1279534
Operable Unit: 01
Material ID: 2284597
Material Code: 0013
Material Name: lube oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: Not reported
Oxygenate: Not reported